

## **PARKING STRUCTURE ISSUES**

- **HYDROCARBONS FOUND IN SOIL AT CONCENTRATIONS RANGING FROM NON/DETECT TO 570 PPM**
- **EVIDENCE OF DUMPED MATERIALS AT ONE BORING LOCATION**
- **ONE SAMPLE SHOWS CONTAMINATION AT 20 FOOT DEPTH**

## **PARKING STRUCTURE PROPOSED PLAN OF ACTION**

- **INVESTIGATE FOOTPRINT AREA OF  
STRUCTURE WHEN ASPHALT IS REMOVED**
- **CONCENTRATE IN AREAS OF KNOWN  
CONTAMINATION (TPH & OTHERS)**
- **EXCAVATE TO LESS THAN 100 PPM TPH**
- **VERIFY WITH CONFIRMATION SAMPLING**
- **UTILIZE STRUCTURE TO CAP REMAINING  
HYDROCARBONS (< 100 PPM)**
- **WILL CONCLUDE "DUE DILIGENCE" EFFORTS  
FOR THE FURTHER INVESTIGATION OF AREA  
COVERED BY THE STRUCTURE**